


DATE:	CONNECTION DIAGRAM	CATALOG NO.:
May 1, 2014		KG1504



SCHEMATIC DIAGRAM - 6 LEADS

VOLTAGE	CONNECTION	ROTATION (VIEWED FROM DRIVE END)
2300	<p>The diagram shows three supply lines labeled L1, L2, and L3. The motor windings are connected in a star configuration. Terminal T1 is connected to L1, T2 to L2, and T3 to L3. The other terminals (T4, T5, T6) are shorted together at the center point.</p>	
4160	<p>The diagram shows three supply lines labeled L1, L2, and L3. The motor windings are connected in a delta configuration. Terminal T1 is connected to L1, T2 to L2, and T3 to L3. The other terminals (T4, T5, T6) are shorted together in a triangle.</p>	

TECO **Westinghouse**

DWG. NO.
3A061H475