


DATE:

June 29, 2005

CONNECTION DIAGRAM

CATALOG NO.:

KG4508R



SCHEMATIC DIAGRAM - 6 LEADS

VOLTAGE	CONNECTION	ROTATION (VIEWED FROM DRIVE END)
2300	<p>Winding connection diagram for 2300V. It shows a star (Y) connection of the motor windings. The supply lines are labeled L1, L2, and L3. The motor leads are labeled T1, T2, T3, T4, T5, and T6.</p>	<p>A curved arrow indicating clockwise rotation when viewed from the drive end.</p>
4160	<p>Winding connection diagram for 4160V. It shows a delta (Δ) connection of the motor windings. The supply lines are labeled L1, L2, and L3. The motor leads are labeled T1, T2, T3, T4, T5, and T6.</p>	<p>A curved arrow indicating clockwise rotation when viewed from the drive end.</p>

TECO  **Westinghouse**

DWG. NO.

3A061H475