


DATE:	CONNECTION DIAGRAM	CATALOG NO.:
June 30, 2005		P1004



SCHEMATIC DIAGRAM - 6 LEADS

VOLTAGE	CONNECTION	ROTATION (VIEWED FROM DRIVE END)
2300	<p>Diagram showing a star connection for a 2300V motor. Three supply lines L1, L2, and L3 are connected to the top leads T1, T2, and T3. The bottom leads T4, T5, and T6 are connected to a common star point.</p>	
4160	<p>Diagram showing a star connection for a 4160V motor. Three supply lines L1, L2, and L3 are connected to the top leads T1, T2, and T3. The bottom leads T4, T5, and T6 are connected to a common star point.</p>	

TECO **Westinghouse**

DWG. NO.
3A061H475